



AK 10



AK 20



AK 30

## AK SYSTEM BATTERIES

### Battery Charging Times - Minutes (80%/100% capacity)

<b>AL 101 CHARGER</b> 	70/95	135/180	160/205
<b>AL 300 CHARGER</b> 	30/45	35/55	35/60
<b>AL 500 CHARGER</b> 	30/45	35/55	35/60

### Run Times Per Battery Charge - Minutes<sup>1</sup>

<b>MSA 120 C-B</b>	18*	<b>40</b>	55
<b>MSA 140 C-B</b>	18*	40*	<b>45</b>
<b>FSA 57</b>	<b>25</b>	50	60
<b>NEW! FSA 60 R</b>	13	<b>25</b>	32
<b>HLA 56</b>	50	<b>100</b>	120
<b>HSA 56</b>	<b>50</b>	100	120
<b>BGA 57</b>	13	<b>25</b>	30
<b>NEW! SHA 56</b> (WHEN OPERATING IN SHREDDER MODE)	12	<b>25</b>	30

### Working Range Per Battery Charge - Sq. Ft.<sup>1</sup>

<b>RMA 460</b>	-	-	<b>2,852</b>
<b>RMA 460 V</b>	-	-	<b>2,347</b>

\*Reduced tool performance

— Not Applicable

**Note:** Battery/tool combinations providing the best balance, adequate run time and performance are shown in bold.